

THE WARBLETON PARISH FINGER POST SURVEY
MARCH 2021

Finger Post A

Location: Kingsley Hill/Chapmans Town Road

Grid Ref: 616180

Condition:

Post: rotting badly and leaning

Arms: rotten

Paint: poor

Letters: ok

Comments: Urgently needs replacing

Finger Post B

Location: North Road/Causeway (White Horse)

Grid Ref: 651146

Condition:

Post: rotting

Arms: unstable

Paint: shabby

Letters: ok

Comments: Poor condition, needs replacing

Finger Post C

Location: Sandhill Lane/Bodle Street Road

Grid Ref: 643163

Condition:

Post: rotten

Arms: rotten

Paint: poor

Letters: poor

Comments: Poor condition, needs replacing

Finger Post D

Location: Rookery Lane/Rushlake Green

Grid Ref: 628184

Condition:

Post: rotting

Arms: ok

Paint: poor

Letters: ok (H missing)

Comments: Will need replacing in due course

Finger Post E

Location: Middle Lane/Rushlake Green

Grid Ref: 627185

Condition:

Post: slight rotting at base

Arms: ok

Paint: poor

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post F

Location: Marklye Lane/Rushlake Green

Grid Ref: 626185

Condition:

Post: ok

Arms: ok

Paint: poor

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post G

Location: Padgham Lane/Churches Green Lane

Grid Ref: 654179

Condition:

Post: unsteady and leaning

Arms: 2 ok, 1 missing ?

Paint: shabby

Letters: ok

Comments: requires replacing, phone/electrical cable wrapped around it

Finger Post H

Location: Church Hill/Foords Lane

Grid Ref: 611181

Condition:

Post: rotting at base and leaning

Arms: ok

Paint: shabby

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post I

Location: Chapmans Town Road/Marklye Lane

Grid Ref: 619195

Condition:

Post: ok

Arms: ok

Paint: shabby

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post J

Location: Rookery Lane/Goldings Lane

Grid Ref: 639193

Condition:

Post: ok

Arms: ok

Paint: ok

Letters: ok

Comments: good condition

Finger Post K

Location: Foords Lane/Hammer Lane

Grid Ref: 606165

Condition:

Post: base rotten and leaning slightly

Arms: ok

Paint: ok

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post L

Location: Back Lane/Cowbeech Road

Grid Ref: 625179

Condition:

Post: rotting

Arms: ok

Paint: shabby

Letters: ok

Comments: currently serviceable, but post requires replacement in 12 months

Finger Post M

Location: Whitebirch Lane/Marklye Lane

Grid Ref: 616200

Condition:

Post: ok

Arms: ok

Paint: shabby

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post N

Location: Barley Mow Lane/Gibsons Lane

Grid Ref: 617198

Condition:

Post: ok

Arms: ok

Paint: shabby

Letters: ok

Comments: currently serviceable, check in 12 months

Finger Post O

Location: Outside Rushlake Green village shop

Grid Ref: 625180

Condition:

Post: ok

Arms: ok

Paint: ok

Letters: ok

Comments: good condition

Finger Post P

Location: Goldings Lane/Middle Lane (Turners Green) Grid Ref: 635196

Condition:

Post: ok
Arms: ok
Paint: ok
Letters: ok
Comments: good condition

Finger Post Q

Location: Tilley Lane/Prinkle Lane

Grid Ref: 665137

Condition:

Post: ok
Arms: ok
Paint: ok
Letters: ok
Comments: good condition

Finger Post R

Location: Foords Lane/Cowden Hall Lane

Grid Ref: 601166

Condition:

Post: ok
Arms: ok
Paint: ok
Letters: ok
Comments: good condition

Finger Post S

Location: Kingsley Hill/Cowbeech Road

Grid Ref: 624177

Condition:

Post: ok
Arms: ok
Paint: ok
Letters: ok
Comments: good condition

Finger Post T

Location: Middle Lane/B2096 (Three Cups Corner) Grid Ref: 635202

Condition:

Post: ok
Arms: ok
Paint: ok
Letters: ok
Comments: good condition